

The City of Springdale

Challenge

Springdale Arkansas experienced a harsh flood in May two thousand nineteen. The flood caused a lot of wash out throughout the city. Overtime the sidewalks around the city began to sink due to the wash out. When soil is washed from underneath the slab this is the typical outcome due to voiding under the area. The City turned to Vesta Foundation Solutions to help them solve their problem.

Solution

A Vesta Foundation Solutions Diagnostics and design rep inspected several locations that the City of Springdale was concerned about. The Representative collected all necessary information for our team to begin assisting the city. The Vesta Representative proposed the best solution for the job, which would save the city time and money. PolyLevel foam injection is the method that the Vesta team uses to lift and stabilize concrete slabs that have sunken down. The Vesta production team was able to smoothly execute the proposed solution restoring the City of Springdale's sidewalks.



Sidewalk lift & level



Foundation Solutions